

ISO Tolerance za luknje (ISO 286-2) +H12+H13+P9 © UL-FS, KMTM, CeMEK 2008

	- polje <i>H</i> (1.prioriteta)			- 1. prioriteta			- 2. prioriteta			- tolerance za posebne namene											
Imenska velikost čepa (mm) in odstopki od imenske velikosti v mikrometrih (µm)																					
Nad	3	6	10	18	24	30	40	50	65	80	100	120	140	160	180	200	225	250	280	315	355
vklj.	6	10	18	30	30	40	50	65	80	100	120	140	160	180	200	225	250	280	315	355	400
A11	+345 +270	+370 +280	+400 +290	+430 +300	+430 +300	+470 +310	+480 +320	+530 +340	+550 +360	+600 +380	+630 +410	+710 +460	+770 +520	+830 +580	+950 +660	+1030 +740	+1110 +820	+1240 +920	+1370 +1050	+1560 +1200	+1710 +1350
B11	+215 +140	+240 +150	+260 +150	+290 +160	+290 +160	+330 +170	+340 +180	+380 +190	+390 +200	+440 +220	+460 +240	+510 +260	+530 +280	+560 +310	+630 +340	+670 +380	+710 +420	+800 +480	+860 +540	+960 +600	+1040 +680
C11	+145 +70	+170 +80	+205 +95	+240 +110	+240 +110	+280 +120	+290 +130	+330 +140	+340 +150	+390 +170	+400 +180	+450 +200	+460 +210	+480 +230	+530 +240	+550 +260	+570 +280	+620 +300	+650 +330	+720 +360	+760 +400
D9	+60 +30	+76 +40	+93 +50	+117 +65	+117 +65	+142 +80		+174 +100		+207 +120		+245 +145		+285 +170		+320 +190		+350 +210			
D10	+78 +40	+98 +40	+120 +50	+149 +65	+149 +65	+180 +80		+220 +100		+260 +120		+305 +145		+355 +170		+400 +190		+440 +210			
D11	+105 +30	+130 +40	+160 +50	+195 +65	+195 +65	+240 +80		+290 +100		+340 +120		+395 +145		+460 +170		+510 +190		+570 +210			
E8	+38 +20	+47 +25	+59 +32	+73 +40	+73 +40	+89 +50		+106 +60		+126 +72		+148 +85		+172 +100		+191 +110		+214 +125			
E9	+50 +20	+61 +25	+75 +32	+92 +40	+92 +40	+112 +50		+134 +60		+159 +72		+185 +85		+245 +100		+285 +110		+320 +125		+355 +151	
E10	+68 +20	+83 +25	+102 +32	+124 +40	+124 +40	+150 +50		+180 +60		+212 +72		+245 +85		+285 +100		+320 +110		+355 +125			
F7	+22 +10	+28 +13	+34 +16	+41 +20	+41 +20	+50 +25		+60 +30		+71 +36		+83 +43		+96 +50		+108 +56		+119 +62			
F8	+28 +10	+35 +13	+43 +16	+53 +20	+53 +20	+64 +25		+76 +30		+90 +36		+106 +43		+122 +50		+137 +56		+151 +62			
F9	+40 +10	+49 +13	+59 +16	+72 +20	+72 +20	+87 +25		+104 +30		+123 +36		+143 +43		+165 +50		+186 +56		+202 +62			
G6	+12 +4	+14 +5	+17 +6	+20 +7	+20 +7	+25 +9		+29 +10		+34 +12		+39 +14		+44 +15		+49 +17		+54 +18			
G7	+16 +4	+20 +5	+24 +6	+28 +7	+28 +7	+34 +9		+40 +10		+47 +12		+54 +14		+61 +15		+69 +17		+75 +18			
H6	+8 0	+9 0	+11 0	+13 0	+13 0	+16 0		+19 0		+22 0		+25 0		+29 0		+32 0		+36 0			
H7	+12 0	+15 0	+18 0	+21 0	+21 0	+25 0		+30 0		+35 0		+40 0		+46 0		+52 0		+57 0			
H8	+18 0	+22 0	+27 0	+33 0	+33 0	+39 0		+46 0		+54 0		+63 0		+72 0		+81 0		+89 0			
H9	+30 0	+36 0	+43 0	+52 0	+52 0	+62 0		+74 0		+87 0		+100 0		+115 0		+130 0		+140 0			
H11	+75 0	+90 0	+110 0	+130 0	+130 0	+160 0		+190 0		+220 0		+250 0		+290 0		+320 0		+360 0			
Js6	+4 -4	+4.5 -4.5	+5.5 -5.5	+6.5 -6.5	+6.5 -6.5	+8 -8		+9.5 -9.5		+11 -11		+12.5 -12.5		+14.5 -14.5		+16 -16		+18 -18			
Js7	+6 -6	+7.5 -7.5	+9 -9	+10.5 -10.5	+10.5 -10.5	+12.5 -12.5		+15 -15		+17.5 -17.5		+20 -20		+23 -23		+26 -26		+28.5 -28.5			
Js8	+9 -9	+11 -11	+13.5 -13.5	+16.5 -16.5	+16.5 -16.5	+19.5 -19.5		+23 -23		+27 -27		+31.5 -31.5		+36 -36		+40.5 -40.5		+44.5 -44.5			
K6	+2 -6	+2 -7	+2 -9	+2 -11	+2 -11	+3 -13		+4 -15		+4 -18		+4 -21		+5 -24		+5 -27		+7 -29			
K7	+3 -9	+5 -10	+6 -12	+6 -15	+6 -15	+7 -18		+9 -21		+10 -25		+12 -28		+13 -33		+16 -36		+17 -40			
K8	+5 -13	+6 -16	+8 -19	+10 -23	+10 -23	+12 -27		+14 -32		+16 -38		+20 -43		+22 -50		+25 -56		+28 -61			

Nad	3	6	10	18	24	30	40	50	65	80	100	120	140	160	180	200	225	250	280	315	355
vklj.	6	10	18	30	30	40	50	65	80	100	120	140	160	180	200	225	250	280	315	355	400
M6	-1 -9	-3 -12	-4 -15	-4 -17	-4 -17	-4 -20		-5 -24		-6 -28		-8 -33			-8 -37			-9 -41		-10 -46	
M7	0 -12	0 -15	0 -18	0 -21	0 -21	0 -25		0 -30		0 -35		0 -40			0 -46			0 -52		0 -57	
M8	+2 -16	+1 -21	+2 -25	+4 -29	+4 -29	+5 -34		+5 -41		+6 -48		+8 -55			+9 -63			+9 -72		+11 -78	
N6	-5 -13	-7 -16	-9 -20	-11 -24	-11 -24	-12 -28		-14 -33		-16 -38		-20 -45			-22 -51			-25 -57		-26 -62	
N7	-4 -16	-4 -19	-5 -23	-7 -28	-7 -28	-8 -33		-9 -39		-10 -45		-12 -52			-14 -60			-14 -66		-16 -73	
N8	-2 -20	-3 -25	-3 -30	-3 -36	-3 -36	-3 -42		-4 -50		-4 -58		-4 -67			-5 -77			-5 -86		-5 -94	
P6	-9 -17	-12 -21	-15 -26	-18 -31	-18 -31	-21 -37		-26 -45		-30 -52		-36 -61			-41 -70			-47 -79		-51 -87	
P7	-8 -20	-9 -24	-11 -29	-14 -35	-14 -35	-17 -42		-21 -51		-24 -59		-28 -68			-33 -79			-36 -88		-41 -98	
P8	-12 -30	-15 -37	-18 -45	-22 -55	-22 -55	-26 -65		-32 -78		-37 -91		-43 -106			-50 -122			-56 -137		-62 -151	
R6	-12 -20	-16 -25	-20 -31	-24 -37	-24 -37	-29 -45		-35 -54	-37 -56	-44 -66	-47 -69	-56 -81	-58 -83	-61 -86	-68 -97	-71 -100	-75 -104	-85 -117	-89 -121	-97 -133	-103 -139
R7	-11 -23	-13 -28	-16 -34	-20 -41	-20 -41	-25 -50		-30 -60	-32 -62	-38 -73	-41 -76	-48 -88	-50 -90	-53 -93	-60 -106	-63 -109	-67 -113	-74 -126	-78 -130	-87 -144	-93 -150
R8	-15 -33	-19 -41	-23 -50	-28 -61	-28 -61	-34 -73		-41 -87	-43 -89	-51 -105	-54 -108	-63 -126	-65 -128	-68 -131	-77 -149	-80 -152	-84 -156	-94 -175	-98 -179	-108 -197	-114 -203
S6	-16 -24	-20 -29	-25 -36	-31 -44	-32 -44	-38 -54		-47 -66	-53 -72	-64 -86	-72 -94	-85 -110	-93 -118	-101 -126	-113 -142	-121 -150	-131 -160	-149 -181	-161 -193	-179 -215	-197 -233
S7	-15 -27	-17 -32	-20 -38	-27 -48	-27 -48	-34 -59		-42 -72	-48 -78	-58 -93	-66 -101	-77 -117	-85 -125	-93 -133	-105 -151	-113 -159	-123 -169	-138 -190	-150 -202	-169 -226	-182 -244
T6						-37 -50	-43 -59	-49 -65	-60 -79	-69 -88	-84 -106	-97 -119	-115 -140	-127 -152	-139 -164	-157 -186	-171 -200	-187 -216	-209 -241	-231 -263	-257 -293
T7						-33 -54	-39 -64	-45 -70	-55 -85	-64 -94	-78 -113	-91 -126	-107 -147	-119 -159	-131 -171	-149 -195	-163 -209	-179 -225	-198 -250	-220 -272	-247 -304

Nad	3	6	10	18	24	30	40	50	65	80	100	120	140	160	180	200	225	250	280	315	355
vklj.	6	10	18	30	30	40	50	65	80	100	120	140	160	180	200	225	250	280	315	355	400
E6	+28 +20	+34 +25	+43 +32	+53 +40	+53 +40	+66 +50		+79 +60		+94 +72		+110 +85			+129 +100			+142 +110		+161 +125	
E7	+32 +20	+40 +25	+50 +32	+61 +40	+61 +40	+75 +50		+90 +60		+107 +72		+125 +85			+146 +100			+162 +110		+185 +125	
E11	+95 +20	+115 +25	+142 +32	+170 +40	+170 +40	+210 +50		+250 +60		+292 +72		+335 +85			+390 +100			+430 +110		+485 +125	
E12	+140 +20	+175 +25	+212 +32	+250 +40	+250 +40	+300 +50		+360 +60		+422 +72		+485 +85			+560 +100			+630 +110		+695 +125	
E13	+200 +20	+245 +25	+302 +32	+370 +40	+370 +40	+440 +50		+520 +60		+612 +72		+715 +85			+820 +100			+920 +110		+1 015 +125	
F6	+18 +10	+22 +13	+27 +16	+33 +20	+33 +20	+41 +2		+49 +30		+58 +36		+68 +43			+79 +50			+88 +56		+98 +62	
G8	+22 +4	+27 +5	+33 +6	+40 +7	+40 +7	+48 +9		+56 +10		+66 +12		+77 +14			+87 +15			+98 +17		+107 +18	
H10	+48 0	+58 0	+70 0	+84 0	+84 0	+100 0		+120 0		+140 0		+160 0			+185 0			+210 0		+230 0	
J6	+5 -3	+5 -4	+6 -5	+8 -5	+8 -5	+10 -6		+13 -6		+16 -6		+18 -7			+22 -7			+25 -7		+29 -7	
J7	+6 -6	+8 -7	+10 -8	+12 -9	+12 -9	+14 -11		+18 -12		+22 -13		+26 -14			+30 -16			+36 -16		+39 -18	
J8	+10 -8	+12 -10	+15 -12	+20 -13	+20 -13	+24 -15		+28 -18		+34 -20		+41 -22			+47 -25			+55 -26		+60 -29	